				. DISTRICT CODE/NAME (200, Oregon CUSD 220					3. FACILITY CODE/NAME OREGON HIGH SCHOOL					
1	r	Rule Violated	Description of	Daganaman dation	Action	Priority Code	Specification(s)	Units Of Measure	Quantity	Labor Code	Estimated Cost	ISBE	Estimated Completion Date	Funding Type
1	Band Room	185.800	Existing fixed auditorium type seating in the Band Room is in poor condition and they are original to when the building was built. Parts are not available so they cannot be repaired properly causing a safety hazard to end users.	See specifications.	е	ხ.	Remove and replace the auditorium seating.	lump sum	300	2	\$100,000.00		9/1/2024	F
2	HVAC compressors	185.455	Existing compressors for HVAC equipment has failed and require replacement and cannot be repaired.	See specifications.	е	b.	Remove and replace the compressors.	lump sum	5	2	\$25,800.00		9/1/2024	F
3	Kitchen	Emergency Food Storage	Existing freezer stopped working and repairs could not be made to make it operate again. Without the freezer, the District would have had to close school because of the lack of food storage space.	See specifications.	е	b.	Remove and install a new freezer in the kitchen.	lump sum	1	2	\$15,700.00		9/1/2024	F

Violation / Work Item Listing