HEALTH/LIFE SAFETY EMERGENCY BOARD RESOLUTION

School Name and Address
David L. Rahn Jr. High School
105 W. Brayton Street
Mt. Morris, IL. 61054
District
Oregon CUD 220
County
Ogle

INSTRUCTIONS: Requires two signed and dated copies submitted to Regional Superintendent and State Board of Education.

EMERGENCY SITUATION:

The boiler at DLR is not functioning. We have discovered that there is a leak inside the tank that needs to be repaired. In addition, the leak flooded the compartment that contained the boiler's electronic components. The building is able to stay open during the repair but if there were to be a problem with our other boiler we would need to close school. Both boilers are the same model and same year.

FUNDING:		BIDDING:								
	on and Safety Financing will o address the emergency.									
X HLS Fu	unds Available		Work will be	bid						
OR			OR							
☐ HLS Fun	ds need to be raised	☐ Bidding requirements will be exempt								
	URES TO CONTINUE OPERATIONS: remaining boiler to heat the building.									
RESOLUTION M	RESOLUTION MOTION:									
Date of Board Meeting										
Number of Board Members Vote:										
Number Against Number in Favor										
SIGNATURES:										
Date	Board President		Date	District Superintendent						
Date	Secretary of the Board		Date	Regional Superintendent						

Form 36-20 (3/04) (Prescribed by Regional Superintendent for local board use)

180.530 b)4)c)

HEALTH/LIFE SAFETY EMERGENCY BOARD RESOLUTION

School Name and Address
David L. Rahn Jr. High School
Oregon CUD 220

105 W. Brayton Street
Mt. Morris, IL. 61054
District
Oregon CUD 220
County
Ogle

INSTRUCTIONS: Requires two signed and dated copies submitted to Regional Superintendent and State Board of Education.

EMERGENCY SITUATION:

Another boiler at DLR is not functioning. We have discovered that there is a leak inside the tank that needs to be repaired. In addition, the leak flooded the compartment that contained the boiler's electronic components. The building is able to stay open during the repair but if there were to be another problem with our other boiler we would need to close school.

FUNDING:										
		BIDDING:								
	on and Safety Financing will o address the emergency.									
X HLS Fu	inds Available		Work will be	e bid						
OR			OR							
☐ HLS Fund	ds need to be raised	☐ Bidding requirements will be exempt								
	URES TO CONTINUE OPERATIONS: remaining boiler to heat the building.									
RESOLUTION M	RESOLUTION MOTION:									
Date of Board	Meeting									
Number of Bo	pard Members									
Vote:										
Number Against										
Number i	in Favor									
SIGNATURES:										
Date	Board President		Date	District Superintendent						
Date	Secretary of the Board		Date	Regional Superintendent						

Form 36-20 (3/04) (Prescribed by Regional Superintendent for local board use)

180.530 b)4)c)

				2200, Ore	2200, Oregon CUSD 220				3. FACILITY CODE/NAME BLACK HAWK JR HIGH SCHOOL						
- 1 1		Location(s) (Room No)		Description of the violation	Recommendation to correct violation	Action I.D.	Priority Code	Specification(Units Of Measure	Quantity	Labor Code	Estimated Cost	ISBE Adjustment	Estimated Completion Date	Funding Type
		Boiler Room	185.495	I	See specifications.	е		Repair water leak in Boiler and 2.	1 lump sum	2	2	\$16,896.87		3/1/2022	F

Violation / Work Item Listing