

1. COUNTY CODE <b>071, Ogle</b>				2. DISTRICT CODE/NAME <b>2200, Oregon CUSD 220</b>				3. FACILITY CODE/NAME <b>OREGON HIGH SCHOOL</b>						
Item I.D.	Location(s) (Room No)	Rule Violated	Description of the violation	Recommendation to correct violation	Action I.D.	Priority Code	Specification(s)	Units Of Measure	Quantity	Labor Code	Estimated Cost	ISBE Adjustment	Estimated Completion Date	Funding Type
1	Boiler Room	BOCA 1996	Existing hot water storage tank requires replacement due to its condition.	See specifications.	e	b.	Remove and replace the hot water storage tank.	lump sum	1	2	\$8,500.00		9/1/2022	F

Violation / Work Item Listing